

FIG. 1




FIG. 2




FIG. 3




FIG. 4






FIG. 5A**FIG. 5B**

TEMPERATURE/BIAS DEPENDENCE

FIG. 5C




FIG. 6




FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15B





FIG. 15A








FIG. 19

